

1-4 Parts list




Fig.4

Table 1

No.	Part name	Quantity	No.	Part name	Quantity
1	Body	1	16	Set screw	1
2	Wedge plunger	1	17	Set screw	1
3	Master jaw	2or3	18	Grease nipple	2or3
4	Soft jaw	2or3	19	Steel ball	1
5	T nut	2or3 ^{*1}	20	Handle	1 ^{*5}
6	Cover	1	21	Hex key	1 ^{*6}
7	Draw screw	1	22	Hex key	1
8	Draw tube	1 ^{*2}	23	Hex key	1
9	Draw nut	1	24	Hex key	1
10	Spring	1	25	Hex key	1
11	Lead ball	1	26	Hex key	1
12	Stop bolt	2or3	27	Hex key	1
13	Chuck attaching bolt	6 ^{*3}			
14	Socket head cap screw	3or4 ^{*4}	28	Back plate	1 ^{*7}
	Machine screw		29	Socket head cap screw	3 ^{*7}
15	Jaw attaching bolt	4or6			

*1. N-15 or more: 6 pieces.

*2. Exclude 4" and 5".

*3. N-04, N-05, NL04 and NL05 : 3 pieces. NT04 and NT05 : 4 pieces.

*4. 4" and 5" : Machine screw, 6" or more : Socket Head cap screw.

*5. 6" or more. (Exclude NL12)

*6. 4", 5" and NL12.

*7. Only supplied if there is a back plate.